# **Combination Clamping Bars**

1586,400



## **Product Description**

The combination clamping bar offers 3 ways to clamp/support the workpiece:

· Floating mode

Floating mode is used to clamp and support additional clamping points on components.

Centric mode

The jaws of the clamping bar move in sync. The centre axis of the workpiece remains unchanged even if the outer diameters are modified.


· Machine vice mode


When this mode is selected, one of the jaws is locked in place on the clamping bar. The second jaw remains movable.

#### Material

· Tool steel, hardened

## **Drawing**





floating mode

Erwin Halder KG

machine vice mode

### **Order information**

i e	Art. No.
[9]	
5360	1586.400



Page 1 of 1 Published on: 14.3.2018